Oil Field Environmental Incident Summary

County: WILLIAMS Twp: 157 Rng: 99 Sec: 34 Qtr: SE SW Location Description: Spill happened in the Northeast corner of the constructed pad; however, the

wind blow it off location going back to the Northwest.

Submitted By: Chance Scally Received By:

Contact Person: Pete Larsen

9821 KATY FREEWAY, STE 460

HOUSTON, TX 77024

General Land Use: Pasture Affected Medium: Topsoil

Distance Nearest Occupied Building:1 MileDistance Nearest Water Well:1 Mile

Type of Incident: Treater Popoff

Release Contained in Dike: No Reported to NRC: No

Spilled Units Recovered Units Followup Units

Oil 5 Gallons

Brine Other

Description of Other Released Contaminant:

NA

Inspected: Written Report Received: Clean Up Concluded:

Risk Evaluation:

None

Areal Extent:

Approximately 100 sq. ft

Potential Environmental Impacts:

None

Action Taken or Planned:

Fresh watered flow line, removed any blockage. We will up our fresh water treatment and have pumpers pulling salinity tests ever week keeping a close eye on the well.

Wastes Disposal Location: Waiting on land owner to view and will place recovered waste in flare

pit.

Agencies Involved: Gunther Harms with NDIC was notified.

Updates

Date: 6/6/2017 Status: Inspection Author: Torgerson, Brad

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Visited the site on 6/6/2017 at 11:14 am - Mostly Sunny and 63 Degrees F- What appeared to be crude oil impacted grass and soil was observed off of the location to the NW of the facility flare. Crude oil impacted soils were also observed on the location in the vicinity of the flare. Clean-up appears to be necessary.